

SAPC-10716

Copy / of 5

13 November 1956

MEMORANDUM FOR: Contracting Officer

SUBJECT : Comments on IN-08307 from [REDACTED]

25X1A6c

FOIAb3a 1. The first sentence of Paragraph 2 is without foundation. [REDACTED], although instructed to monitor System Three work as a fifth priority function (System Four, System One, System Four read-out and System One read-out problems are of higher priority), has not contacted the Ramo-Wooldridge people on System Three, has not seen any of the hardware nor test results and has not been consulted by R-W personnel on any phase of the System Three receiver.

2. By phone on 5 November, Burt stated that seven System Three's, in addition to the two delivered, would be ready within a week. They are ready excepting for an insulation breakdown problem. Burt stated that he would supply replacement boards to Detachment B for the two they have and expedite any other maintenance parts requested by the Detachment.

3. Paragraph 7 - Special Equipment. The noisy effect mentioned has been found to exist in part at least, within the battery-powered transistorized preamplifier obtained by [REDACTED] from Commo.

25X1A9a

4. The antenna tuning range problem was the result of insufficient test facility at R-W and has been resolved.

25X1A9a

ESO/JFS:jd (13 Nov 56)

Distribution:

Copies 1 and 2 - [REDACTED]
3 and 4 - ESO
5 - Project Chron

25X1A9a

DOCUMENT NO. [REDACTED]
NO CHANGE IN CLASS. [REDACTED]
IT DECLASSIFIED [REDACTED]
CLASS. CHANGED TO: TS S [REDACTED] 2011
NEXT REVIEW DATE: [REDACTED]
AUTH: HR 70-2
DATE 12/11/81 REVIEWER: 037169

25X1A